



**ATTENTION: Official Inspection Stations, Quality Assurance Officers,
and Pennsylvania State Police**

EB20-01

Vehicle Inspection Division Bulletin

February 2020

**TOPICS IN THIS BULLETIN: REMINDER: Testing Vehicles With Capless Fuel Filler
Systems On New OBD/Visual Emission Equipment**

**Testing Vehicles With Capless Fuel Filler Systems On New OBD/Visual Emission
Equipment:**

As a reminder, the new OBD/VISUAL emissions testing equipment includes the ability to capture whether or not a vehicle has a Capless Fuel Filler System. The new equipment software guides the inspector through a series of questions to collect all necessary data. To clarify how these questions should be answered, the following is being provided. (Note: The guidance below supersedes any and all previous instruction associated with LEGACY OBD/Visual equipment which has been completely discontinued.)

When testing a vehicle with a Capless Fuel Filler System on the new equipment, you will need to answer "Yes" to the first three questions of:

1. Is the vehicle Fuel Cap present?
2. Is the Fuel Cap Accessible? and
3. Can the Fuel Cap be Removed?

After collecting the required answers to the first three questions, the software asks, "Does the vehicle have a Capless Fuel Filler System?" Answer "Yes" to this question and the software appropriately bypasses the Adapter question and proceeds to the next testing phase.

Please call the Inspection Station Operator hotline at 1-888-265-5909 if you have any questions.

Anita M. Wasko, Director
Bureau of Motor Vehicles

Stephen J. Madrak, Chief
Vehicle Inspection Division